


災害名：令和3年7月豪雨災害(7/7～8)
査定番号：33-16
地区名：琴浦町槻下

査定設計書添付写真


撮影年月日：令和3年11月1日

写真撮影位置図



全 景

①



全 景

復旧延長 L=98.50m



30.00m

NO.2


NO.3

②




全 景

③



全 景

復旧延長 L=98.50m



15.00m

18.50m

NO.3

NO.4

NO.5

終点

④



全 景

復旧延長 L=98.50m

15.00m

20.00m

起
点
NO.0

NO.1

NO.2

⑤



全 景

復旧延長 L=98.50m


⑤



全 景

復旧延長 L=98.50m

⑤




⑤


全 景



⑥

起点







断面图

NO. 0


GH=16.40
FH=



⑧

NO.0



境界
境界
CL
1.29m



断面图

NO. 1

GH=16.23
FH=



⑨

NO.1

境界

CL

1.29m


境界




断面图

NO. 2

GH=16.40
FH=



CL



NO.2

⑩

境界
CL

1.29m



境界



断面图

N0. 3

GH=16.40
FH=



NO.3

⑪

境界
CL

1.39m


境界




断面图

NO. 4

GH=15.92
FH=



CL



⑫

NO.4

境界

CL

境界



1.29m



断面图

NO. 5

GH=16.36
FH=



13

NO.5

境界

CL

境界

1.29m



被災状況

NO.1付近

14



被災状況

⑮

NO.3付近



被災状況

①6


NO.4付近



現況法勾配


起点側(1:1.3)

①7




道路幅員

①8



仮設道路

①9




災害名：令和3年7月豪雨災害(7/7～8)
査定番号：33-213
地区名：琴浦町逢束

査定設計書添付写真


撮影年月日：令和3年10月29日

写真撮影位置図



全 景

①



全 景

復旧延長 L=12.00m

8.00m

4.00m

起点
NO.0

NO.1

NO.2
終点



①


①


全 景



②

起点







断面图


NO.0

GH=12.20
FH=12.28



NO.0

④





断面图

NO.1

GH=11.58

FH=12.14



NO.1



⑤



断面图

N0.2

GH=11.98
FH=12.09



NO.2

⑥



被災状況

NO.0付近

⑦



被災状況

NO.1付近

⑧



被災状況

NO.2付近

⑨



現況法勾配

終点側(1:1.5)

⑩



既設水路

⑪



既設取水口

⑫

塩ビ管φ150



舗装状況

⑬

全景



表層



下層路盤



道路幅員

①4

3.30m



既設管水路

ヒューム管φ300



査定杭写真

起点位置 (NO. 0)

起点側より撮影

16

遠景



近景



査定杭写真

終点位置 (NO. 2)

終点側より撮影

17

遠景



近景

